Figure 1

Figure 2




Figure 3




Figure 4




Figure 5




Figure 6a




Figure 6b




Figure 7

COCCES, CHOCL

Figure 8




Figure 9

Figure 10a




Figure 10b

Figure 11a




Figure 11b




Figure 12




Figure 13




Figure 14

| 386 — 388 | | list/of the most likely causes for the specified SYMPTOM | Defect Frequency | Defective Component 58 | Test Error 51 | Damaged 26 | Broken Fiber | Pitted 10 | Insufficient Solder 8 | High Insertion loss 6 | Excessive Solder 5 | Proof Test Break 5 | Wrong Component 5 - 350 |
|-----------|-------------------------|--|--------------------|------------------------|-----------------|-------------------|---------------|-------------------|-----------------------|-----------------------|--------------------|--------------------|-------------------------|
| 387 | 🔏 Troubleshooting Guide | The following is a list/of the m | Defect Category / | Component Defects | Testing Defects | Component Defects | Fiber Defects | Connector Defects | Solder Defects | Testing Defects | Solder Defects | Testing Defects | Component Defects |

Figure 15